

Rockland Energy Advisory Committee  
June 11, 2013

Attendance: Larry Pritchett, Norma Athearn, and Bill Pearce

Revised minutes of May 28, 2013, were reviewed and approved by the Committee.

Of the 12 different places that were leaking on the library building envelope, only two are still leaking. The main entrance has a lot of failing mortar spots. There is still a small leak at the chimney. The insulation project can continue after this leak is resolved.

Some of the downspouts around the library need some review and redirection.

Larry provided a sample of the LED light provided by the manufacturer.